

Bundesstelle für Seeunfalluntersuchung

Federal Bureau of Maritime Casualty Investigation

ECDIS; a grounding avoidance tool? EMAIF 5; 30th - 31st March 2009 Jörg Kaufmann

Outline




A. NAV 54 / MSC 85, 86: mandatory ECDIS carriage requirement


B. groundings in 2008

- in the English Channel; January 08
- in the Caribbean Sea; March 08
- in the Solomon Sea; April 08
- in the Gulf of Suez; May 08
- C. contribution of ECDIS to safety of navigation





















in the Gulf of Suez; May 08; no EC on board






in the Gulf of Suez; May 08; no EC on board






in the Gulf of Suez; May 08; no EC on board






in the Gulf of Suez; May 08; no EC on board






in the Gulf of Suez; May 08; no EC on board





in the Gulf of Suez; May 08; no EC on board






in the Solomon Sea; April 08; no EC on board







in the Solomon Sea; April 08; no EC on board






in the Solomon Sea; April 08; no EC on board

To assist you in your fuel calculations, the distances between the outports are: Port Kelang 2106 Darwin 1070 Port Moresby 269 Alotau 447 Rabaul 164 Kavieng 164 Rabaul 394 Oro Bay 166 Lae 2761 Jakarta. In a separate msg, I will scan you a copy of the area and the route to use.

Pls adv any questions you may have.








in the Solomon Sea; April 08; no EC on board





in the Solomon Sea; April 08; no EC on board





Routeing

Where on several Australian Charts serving the areas covered by this volume, preferred routes are indicated, the term preferred route implies that the route has not been surveyed in accordance with IMO/IHO standards for

Preferred route

in the Solomon Sea; April 08; no EC on bo

Chapter 6 - North-east coast of Papua New Guinea - Kel recommended tracks, but is the preferred route for vessels 148° 150° 1470 149 having regard to charted depths. The attention of vessels Vitiaz Str meeting on the preferred route is drawn to the International NEW BRITAIN Regulations for Preventing Collisions at Sea (1972), conten particularly Rules 18 and 28 in regard to vessels constrained by their draught. For further information see C Cretin Australian Seafarers Handbook and Annual Summary of Australian Notices to Mariners. Solomon Sea PAPUA NEW GUINEA aunhlan Is source: Admiralty sailing Directions, Pacific Islands Pilot, Volume I



in the Caribbean Sea; March 08; no EC on board

On February 29th, 2008 the container vessel "Turin Express" departed at 06:00 hrs lt from Savannah and commenced her sea passage at 09:30 lt.

The vessel's destination was Caucedo, Dominican Republic, with estimated time of arrival March, 3rd, 06:00 hrs lt.

A voyage plan from Pilot to Pilot had been prepared by the Navigation Officer as done before. The vessel headed for the Mona Passage with the intention to continue with the coastal voyage to the port of destination.

Unfortunately the Navigation Officer altered the track of previous voyages closer to the east coast of Hispaniola, passing the center of the Silver Bank, the center to avoid charted reefs in the northeasterly edge of the bank, considering the passage safe and free of underwater reefs.

During his watch the Duty Officer entered the bank and followed the route until a nearby research vessel contacted him by VHF, given warnings about dangerous reefs with the advice to alter the couse by 10 degrees to starboard for a safe passage to which I agreed. Course had been set to 150 degrees and the vessel continued on her passage with the 2nd Officer on duty, assisted by the 3rd Mate. Speed was about 17.5 kts.


When the Duty Officer detected discoloured water close to the port bow, he altered the course to starboard, reduced the speed and called me.

When I arrived on the bridge the vessel hit with her bulbous bow an underwater coral reef and the vessel was shaking and she listed for few seconds to port.






in the Caribbean Sea; March 08; no EC on board





in the Caribbean Sea; March 08; no EC on board






in the English Channel; January 08; ECS on board



T



in the English Channel; January 08; nautical chart





in the English Channel; January 08; Radar / ECS; t ~ -10 min.





in the English Channel; January 08; Radar / ECS; t ~ -6 min.






in the English Channel; January 08; Radar / ECS; t ~ +5 min.






in the English Channel; January 08; ECS; test run






in the English Channel; January 08; ECS; test run








in the English Channel; January 08; ECS; test run






in the English Channel; January 08; ECS; test run





in the English Channel; January 08; ECS; test run





C. safety of navigation

status quo of EC's in BSU marine accident investigations



- number of ships equipped with EC's is increasing, but still there is
 - uncertainty about status ECS or ECDIS
 - insufficient knowledge about functionality
 - ineffective use in voyage planning, execution and monitoring
 - inadequate training



C. safety of navigation



UK NAV 54/14/2:

- NAV 53 debate included issues relating to human element and training aspects
- properly trained mariner using ECDIS with good quality ENCs is significantly less likely to have a navigational accident
- ECDIS also provides significant efficiencies in voyage planning, execution and monitoring
- human element and training issues addressed by STW Sub-Committee



C. safety of navigation

contribution of ECDIS carriage requirement to safety of navigation



- ECDIS can facilitate voyage planning, execution and monitoring
 - reasonable alarm settings here can significantly enhance a safe navigation
 - but it is still the "man" to plan, execute and monitor the voyage, not the "machine"
 - in-depth understanding of the "machine" is paramount for efficient use by the "man"





