

The full, official version of the final report is only available in Hungarian language

**2008-510-5
Railway accident**



On 18 November 2008, a regional passenger train collided with a car at an LC - protected with warning lights and half barriers - between Isaszeg and Gödöllő stations. As a consequence of the accident, the two persons sitting in the car died at the site.

Factual statements directly connected to the occurrence of the accident

The immediate causes of the accident were as follows:

- The warning lights were inoperative (no flashing red lights and open barriers)
- The car did not comply with the traffic regulations regarding passing an LC.

Factual statements indirectly connected to the occurrence of the accident

The LC is constructed in a way that the given train cannot be informed about a fault having developed during the journey of the train.