

The full, official version of the final report is only available in Hungarian language

06. 11. 2006

A passenger train collided with a car at an LC protected with warning lights between Dunakeszi and Rákospalota-Újpest stations. One LC user dies and two seriously injured in the accident.

It was found in the course of the investigation that the warning lights were operating normally at the moment of the collision. The accident happened owing to the inattention of the driver of the car.