

The full, official version of the final report is only available in Hungarian language

2007-323-5

2008-115-5

2008-191-5

2008-211-5

Railway accidents



On 29th August 2007, a regional passenger train collided with a lorry at a normally operating LC - protected by warning lights - between Tócióvölgy and Balmazújváros stations. The engine-driver and three passengers suffered minor injuries as consequence of the accident. The control car of the train and one carriage derailed and toppled to its side.

(3 similar accidents - collisions - happened at the same LC during the year

2008 which were jointly investigated by the IC: 2008-115-5, 2008-191-5, 2008-211-5)

Based on the findings of the site survey and the available data, the IC came to the conclusion that LC AS41 operated normally when the passenger train was approaching it; it signalled 'Stop' towards the road.

The current traffic organisation and the heavy traffic on the road running parallel with the rail track makes it difficult to cross the LC.