

The full, official version of the final report is only available in Hungarian language

2008-130-5

On 21 March 2008 at 9:17 hrs, having departed from track IV and passed exit signal indicating 'Stop', train no. 65540-1 collided with train no. 65411 passing track III at Szerencs station. The two vehicles collided with a little force, therefore only the first right rear-view mirror of the locomotive (reg. no. V43-1060) of train 65540-1 broke.

The IC believes that the occurrence was attributed to human factors and therefore it does not wish to issue safety recommendation.

CONCLUSIONS

Factual statements directly connected to the occurrence of the accident

The engine driver of train no. 65540-1 did not pay sufficient attention to the exit signal indicating Stop, it collided with passing train no. 65411.